

0005

Hidden Splendor Resources

Horizon Mine

3266 South 125 West, Price, Utah 84501

Phone: (435) 636-0820 – Fax: (435) 636-0817

C/007/020 Incoming

cc: Karl

#3516

K

COPY

March 25, 2010

Mr. Jim Smith
Utah Coal Program
Utah Division of Oil, Gas and Mining
1594 West North Temple – Suite 1210
Box 145801
Salt Lake City, UT 84114-5801

Re: C/007/0020 Horizon Mine
2009 Annual Report

Dear Mr. Smith:

Hidden Splendor Resources, Inc. is respectfully submitting two (2) copies of the 2009 Annual Report for the Horizon Mine permit C/007/020. One copy to the Salt Lake Office and one copy to the Price Field Office.

If you have any questions or comments, please feel free to contact me at 435-636-0820.

Sincerely,



Kit Pappas
Manager of Environmental and Engineering Services

Cc: Karl Housekeeper – DOGM (Price Office)
File

File in:

- ☐ Confidential
☒ Shelf
☐ Expandable

Refer to Record No. *0005* Date *03252010*
In C/ *0070020 2010 Incoming*
For additional information

RECEIVED

MAR 29 2010

DIV. OF OIL, GAS & MINING

**AMERICA WEST
RESOURCES, INC.**

**HIDDEN SPLENDOR
RESOURCES, INC.**

HORIZON MINE

**2009
ANNUAL REPORT**

UDOGM PERMIT - C/007/020

This Annual Report shows information the Division has for your mine. Please review the information to see if it is current. If the information needs to be updated please do so in this document. At the end of each section the operator is asked to verify if the information is correct. Please answer these questions and make all comments on this document. Submit the completed document and any additional information identified in the Appendices to the Division by April 30, 2010. During a complete inspection an inspector will check and verify the information. To enter text, click in the cell and type your response. You can use the tab key to move from one field to the next. To enter an X in a box, click next to the box, right click, and select properties, then the checked circle, then hit enter, or hit the unchecked circle if the X is to be removed.

GENERAL INFORMATION

| | |
|--|---|
| Permittee Name | Hidden Splendor Resources Inc. |
| Mine Name | Horizon Mine |
| Operator Name (If other than permittee) | America West Resources, Inc. |
| Permit Expiration Date | October 11, 2011 |
| Permit Number | C/007/0020 |
| Authorized Representative Title | Kit Pappas-Manager of Environmental and Engineering |
| Phone Number | Office 435-636-0820 |
| Fax Number | 801-521-3301 |
| E-mail Address | kit@emerytelcom.net |
| Mailing Address | 3266 South 125 West, Price, Utah 84501 |
| Designated Representative | Kit Pappas |
| Resident Agent | Same as above |
| Resident Agent Mailing Address | Same as above |
| Number of Binders Submitted | 2 |

Operator, please update any incorrect information.

IDENTIFICATION OF OTHER PERMITS

Identify other permits that are required in conjunction with mining and reclamation activities.

| Permit Type | ID Number | Description | Expiration Date |
|-----------------------|---------------|--|-----------------|
| MSHA Mine ID(s) | 42-02074 | Horizon No. 1 Mine | N/A |
| | 42-02075 | Horizon No. 2 Mine (not started) | N/A |
| MSHA Impoundment(s) | | | |
| | | | |
| NPDES/UPDES Permit(s) | UTG040000-001 | Sediment Pond 001 | 4/30/2013 |
| | UTG040000-002 | Mine Discharge (pipe) | 4/30/2013 |
| PSD Permit(s) (Air) | DAQE-700-0 | Modification of Approval Order BAQE-700-0 | N/A |
| | | | |
| Other | | | |
| UDOGM | X/007/0044 | Columbia Well Exploration Permit | N/A |
| | | | |
| | | | |

Operator, please update any incorrect information.

CERTIFIED REPORTS

List the certified inspection reports as required by the rules and under the approved plan that must be periodically submitted to the Division. Specify whether the information is included as Appendix A to this report or currently on file with the Division.

| Certified Reports: | Required | | Included Included | or | DOGM file location Vol, Chapter, Page |
|--------------------|-------------------------------------|-------------------------------------|-------------------------------------|----|--|
| | Yes | No | | | |
| Excess Spoil Piles | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | | |
| Refuse Piles | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | | |
| Impoundments | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | | |
| Other | | | | | |
| | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | |
| | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | |

Operator Comments:

Inspector:

Has the operator complied with this section? Yes ☐ No ☐

Inspector Comments:

COMMITMENTS AND CONDITIONS

The Permittee is responsible for ensuring annual technical commitments in the MRP and conditions accepted with the permit are completed throughout the year. The Division has identified these commitments below and has provided space for you to report what you have done during the past year for each commitment. If the particular section is blank, no commitment has been identified and no response is required for this report. If additional written response is required, it should be filed under Appendix B to this report.

Admin R645-301-100

Soils R645-301-200

Biology R645-301-300

Title: CULTURAL RESOURCES

Objective: If during the course of mining operations, previously unidentified cultural resources are discovered, the Permittee shall ensure that the site(s) is not disturbed and shall notify the Division of Oil, Gas, and Mining. The Division, after coordination with OSM, shall inform the Permittee of necessary actions required.

Frequency: The Permittee shall implement the mitigation measures required by the Division within the time frame specified by the Division.

Status: Ongoing.

Reports: Annual.

Citation: Permit condition Sec. 16.

Operator: Has this commitment been acted on this year?

Yes ☐ No ☐ Not required this year. ☒ If yes, comment;

Operator Comments:

Inspector:

Has the operator complied with this commitment? Yes ☐ No ☐

Inspector Comments:

Title: MACROINVERTEBRATE SURVEY

Objective: Macroinvertebrate surveys of Gordon Creek .2 miles above the confluence of Jewkes Creek and the North fork of Gordon Creek .1 of a mile below the confluence of those streams to monitor potential impacts from mining activities.

Frequency: Every other year.

Status: Ongoing

Reports: Annual.

Citation:: Volume 3, chapter 10 section 10.2.3, page 10-4, paragraph 5.

Operator: Has this commitment been acted on this year?

Yes ☐ No ☐ Not required this year. ☒ If yes, comment;

Operator Comments:

Inspector:

Has the operator complied with this commitment? Yes ☐ No ☐

Inspector Comments:

Title: RAPTOR SURVEY

Objective: An active raptor nest will be verified prior to full pillar extraction being completed within 500 feet of the nest. If the nest is still active full pillar mining will leave a 200-foot barrier around the nest location. If the nest is inactive, a barrier of 100 feet will be left around the nest location. Mitigation of nests either active or inactive lost due to impacts from mining will be replaced under the guidelines and assistance from DWR.

Frequency: Annually.

Status: Ongoing for the life of the mine.

Reports: Annual Report.

Citation: Volume 3, chapter 10 section 10.5.1.2, pages 10-39 and 40, paragraphs 9 and 1.

Operator: Has this commitment been acted on this year?

Yes ☐ No ☐ Not required this year. ☒ If yes, comment;

Operator Comments:

Inspector:

Has the operator complied with this commitment? Yes ☐ No ☐

Inspector Comments:

Title: STREAM BUFFER ZONE PROTECTION

Objective: HSR commits to develop a protection and enhancement plan with DWR and DOGM prior to any secondary or retreat mining under Beaver Creek

Frequency: When second mining under streams occurs.

Status: Check to see if plan has been developed.

Reports: Inspector should check to see if second mining has occurred under streams, annually.

Citation: status Volume 3, chapter 10 section 10.7, page 10-40, paragraph 5.

Operator: Has this commitment been acted on this year?

Yes ☐ No ☐ Not required this year. ☒ If yes, comment;

Operator Comments:

Inspector:

Has the operator complied with this commitment? Yes ☐ No ☐

Inspector Comments:

Landuse, Cultural Resources, Air Quality R645-301- 400

Engineering R645-301-500

Title: SUBSIDENCE CONTROL AND MONITORING

Objective: Pedestrian Survey to be conducted no sooner than 6 months but no later than 12 months after an area has been subsided.

Frequency: Annually.

Status: One going.

Reports: Annual Report.

Citation: 3.4.8.5

Operator: Has this commitment been acted on this year?

Yes ☒ No ☐ Not required this year. ☐ If yes, comment;

Operator Comments: Pedestrian survey in July 2009 revealed no cracks, fractures, slumps or other abnormalities. No second mining was conducted in 2009.

Inspector:

Has the operator complied with this commitment? Yes ☐ No ☐

Inspector Comments:

Geology R645-301-600

Hydrology R645-301-700

Title: COLLECTING AND REPORTING OF BASELINE DATA

Objective: Compare Baseline Data Parameters.

Frequency: Every 5 years during low flow season of the year.

Status: Ongoing until Division releases from commitment.

Reports: Summary in Annual Report during monitoring year.

Citation: Chapter 7, page 7-34.

Operator: Has this commitment been acted on this year?

Yes ☐ No ☐ Not required this year. ☒ If yes, comment;

Operator Comments:

Inspector:

Has the operator complied with this commitment? Yes ☐ No ☐

Inspector Comments:

Bonding & Insurance R645-301-800

Other Commitments

| | |
|--|--|
| | |
| | |

*Reminder: If equipment has been abandoned during 2009, an amendment must be submitted that includes a map showing its location, a description of what was abandoned, whether there were any hazardous or toxic materials and any revision to the PHC as necessary.

REPORTING OF OTHER TECHNICAL DATA

List other technical data and information as required under the approved plan, which must be periodically submitted to the Division. Specify whether the information is included as Appendix B to this report or currently on file with the Division.

Operator Comments:

Inspector:

Has the operator complied with this section? Yes ☐ No ☐

Inspector Comments:

LEGAL, FINANCIAL, COMPLIANCE AND RELATED INFORMATION

Change in administration or corporate structure can often bring about necessary changes to information found in the mining and reclamation plan. The Division is Requesting that each permittee review and update the legal, financial, compliance and related information in the plan as part of the annual report. Please provide the Department of Commerce, Annual Report of Officers, or other equivalent information as necessary to ensure that the information provided in the plan is current. Provide any other change as necessary regarding land ownership, lease acquisitions, legal results from appeals of violations, or other changes as necessary to update information required in the mining and reclamation plan. Include certified financial statements, audits or worksheets, which may be required to meet bonding requirements. Specify whether the information is currently on file with the Division or included as Appendix C to the report.

| Legal / Financial Update | Required | | Included or Included | DOGM File location Vol, Chapter, Page | Comments |
|---|--------------------------|-------------------------------------|--------------------------|--|----------|
| | Yes | No | | | |
| Department of Commerce, Annual Report Officers | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | | |
| Other | | | | | |
| | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | |
| | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | |
| | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | |

Operator Comments:

Inspector:

Has the operator complied fully with this section? Yes ☐ No ☐

Inspector Comments:**MINE MAPS**

Copies of mine maps, current and up-to-date through at least December 31, 2009, are to be provided to the Division as Appendix D to this report in accordance with the requirements of R 645-301-525.240. The map copies shall be made in accordance with 30 CFR 75.1200 as required by MSHA. Mine maps are not considered confidential. (Please provide a CD.)

Confidential information is limited to:

R645-300-124.310. Information that pertains only to the analysis of the chemical and physical properties of the coal to be mined, except information on components of such coal which are potentially toxic in the environment.

R645-300-124.330. Information on the nature and location of archeological resources on public land and Indian land as required under the Archeological Resources Protection Act of 1979 (P. L. 96-95, 93 Stat. 721, 16 U.S.C. 470).

R645-301-322, Fish and Wildlife Information; R645-301-322.100, the scope and level of detail for such information will be determined by the Division in consultation with state and federal agencies with responsibilities for fish and wildlife and will be sufficient to design the protection and enhancement plan required under R645-301-333 and R645-301-322.230, other species or habitats identified through agency consultation as requiring special protection under state or federal law; R645-301-333.300, Include protective measures that will be used during the active mining phase of operation.

The Division will provide procedures, including notice and opportunity to be heard for persons both seeking and opposing disclosure.

Map Number(s)**Map Title/ Description**

| | | | |
|-----------------------|--|--------------------------|--------------------------|
| Annual subsidence map | HORIZON MINE PLAN WITH SUBSIDENCE POINTS | | |
| Mine map | | | |
| Other maps | | Confidential | |
| | | Yes | No |
| | | <input type="checkbox"/> | <input type="checkbox"/> |
| | | <input type="checkbox"/> | <input type="checkbox"/> |
| | | <input type="checkbox"/> | <input type="checkbox"/> |
| | | <input type="checkbox"/> | <input type="checkbox"/> |
| | | <input type="checkbox"/> | <input type="checkbox"/> |
| | | <input type="checkbox"/> | <input type="checkbox"/> |
| | | <input type="checkbox"/> | <input type="checkbox"/> |
| | | <input type="checkbox"/> | <input type="checkbox"/> |

Operator Comments:**Inspector:**

Has the operator complied with this section? Yes ☐ No ☐

Inspector Comments:

OTHER INFORMATION

Please provide any comments of further information to be included as part of the Annual Report. Any other attachments are to be provided as Appendix E to this report. If information is submitted as a group rather than by individual mine, please identify each of the mine's data in the list below.

Additional attachment to this report?

Yes ☒

No ☐

HORIZON WELL MONITORING

Operator Comments:

Inspector:

Has the operator complied with this section? Yes ☐ No ☐

Inspector Comments:

O:\AnnualReport\2009 Annual Reports\Active Mines\Horizon Mine C0070020.doc

APPENDIX A

Certified Reports

Excess Spoil Piles
Refuse Piles
Impoundments

As required under R645-301-514

CONTENTS
QUARTERLY AND ANNUAL POND INSPECTIONS FOR POND 001


| IMPOUNDMENT INSPECTION AND CERTIFIED REPORT | | Page 1 of 1 |
|--|--|-------------------------|
| Permit Number | C/007/020 | Report Date: 02-17-2009 |
| Mine Name | Horizon | |
| Company Name | Hidden Splendor Resources, Inc. | |
| Impoundment Identification | Impoundment Number | 001 |
| | UPDES Permit Number | UTG040019 |
| IMPOUNDMENT INSPECTION | | |
| Inspection Date | 02-17-2009 | |
| Inspected By | Kit Pappas | |
| Reason for Inspection (Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction) | | Quarterly Inspection |
| <p>1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.</p> <p>No signs of instability noted at this incised pond. There is no evidence of slumping in the pond or on the embankment. No hazardous conditions were noted.</p> | | |
| Required for an impoundment which functions as a SEDIMENTATION POND. | <p>2. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and, estimated average elevation of existing sediment.</p> <p>60% Sediment Storage – 7566.9 100 % Sediment Storage – 7569.8 Estimated Sediment Elevation – (Pond Ice-Covered Unable to Estimate)</p> | |
| | <p>3. Principle and emergency spillway elevations.</p> <p>Spillway Elevation - 7573.9 Feet</p> | |
| | <p>4. Field Information</p> <p>Pond covered in ice and snow. The pond was not discharging at the time of inspection. The inlets and outlet were stable. It was discovered during the 3rd Quarter 2008 inspection that the sediment elevation is at clean-out elevation. The pond cleaning will be conducted in Spring of 2009.</p> | |
| | | |

| | | |
|--|---------------------------------|-------------------------|
| IMPOUNDMENT INSPECTION AND CERTIFIED REPORT | | Page 1 of 1 |
| Permit Number | C/007/020 | Report Date: 06-30-2009 |
| Mine Name | Horizon | |
| Company Name | Hidden Splendor Resources, Inc. | |
| Impoundment Identification | Impoundment Number | 001 |
| | UPDES Permit Number | UTG040019 |

IMPOUNDMENT INSPECTION

| | |
|---|---------------------------------|
| Inspection Date | 06-30-2009 |
| Inspected By | Kit Pappas |
| Reason for Inspection (Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction) | Annual and Quarterly Inspection |

1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.
No signs of instability noted at this incised pond. There is no evidence of slumping in the pond or on the embankment. No hazardous conditions were noted.

| | |
|--|--|
| Required for an impoundment which functions as a SEDIMENTATION POND. | 2. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and, estimated average elevation of existing sediment. 60% Sediment Storage – 7566.9 100 % Sediment Storage – 7569.8 Estimated Sediment Elevation – 7567.8 |
| | 3. Principle and emergency spillway elevations. Spillway Elevation - 7573.9 Feet |
| | 4. Field Information Some water in pond. The pond was not discharging at the time of inspection. The inlets and outlet were stable. It was discovered during the 3 rd Quarter 2008 inspection that the sediment elevation is at clean-out elevation. The pond cleaning will be conducted in Summer of 2009. |
| |  |

| IMPOUNDMENT INSPECTION AND CERTIFIED REPORT | | Page 1 of 1 |
|---|---|-------------------------|
| Permit Number | C/007/020 | Report Date: 09-30-2009 |
| Mine Name | Horizon | |
| Company Name | Hidden Splendor Resources, Inc. | |
| Impoundment Identification | Impoundment Number | 001 |
| | UPDES Permit Number | UTG040019 |
| IMPOUNDMENT INSPECTION | | |
| Inspection Date | 09-29-2009 | |
| Inspected By | Kit Pappas | |
| Reason for Inspection (Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction) | | Quarterly Inspection |
| <p>1. Describe any appearance of any instability, structural weakness, or any other hazardous condition. No signs of instability noted at this incised pond. There is no evidence of slumping in the pond or on the embankment. No hazardous conditions were noted.</p> | | |
| Required for an impoundment which functions as a SEDIMENTATION POND. | <p>2. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and, estimated average elevation of existing sediment. 60% Sediment Storage – 7566.9 100 % Sediment Storage – 7569.8 Estimated Sediment Elevation – 7567.8</p> | |
| | <p>3. Principle and emergency spillway elevations. Spillway Elevation - 7573.9 Feet</p> | |
| | <p>4. Field Information Some water in pond. The pond was not discharging at the time of inspection. The inlets and outlet were stable. It was discovered during the 3rd Quarter 2008 inspection that the sediment elevation is at clean-out elevation. The pond cleaning has begun and will continue until completed.</p> | |
| | | |

| IMPOUNDMENT INSPECTION AND CERTIFIED REPORT | | Page 1 of 1 |
|---|---|-------------------------|
| Permit Number | C/007/020 | Report Date: 11-12-2009 |
| Mine Name | Horizon | |
| Company Name | Hidden Splendor Resources, Inc. | |
| Impoundment Identification | Impoundment Number | 001 |
| | UPDES Permit Number | UTG040019 |
| IMPOUNDMENT INSPECTION | | |
| Inspection Date | 11-12-2009 | |
| Inspected By | Kit Pappas | |
| Reason for Inspection (Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction) | | Quarterly Inspection |
| <p>1. Describe any appearance of any instability, structural weakness, or any other hazardous condition. No signs of instability noted at this incised pond. There is no evidence of slumping in the pond or on the embankment. No hazardous conditions were noted.</p> | | |
| Required for an impoundment which functions as a SEDIMENTATION POND. | <p>2. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and, estimated average elevation of existing sediment. 60% Sediment Storage – 7566.9 100 % Sediment Storage – 7569.8 Estimated Sediment Elevation – 7562.0</p> | |
| | <p>3. Principle and emergency spillway elevations. Spillway Elevation - 7573.9 Feet</p> | |
| | <p>4. Field Information Some water in pond. The pond was not discharging at the time of inspection. The inlets and outlet were stable. The pond cleaning has been completed.</p> | |
| | | |

APPENDIX B

Reporting of Technical Data

Including monitoring data, reports, maps, and other information
As required under the approved plan or as required by the Division

In accordance with the requirement of R645-310-130 and R645-301-140

CONTENTS

UNDERGROUND DISCHARGE PUMPING DATA
BIG GAME ROAD KILL REPORT

| <u>DATE</u> | <u>GALLONS PUMPED</u> | <u>MINUTES</u> | <u>AVG. G.P.M.</u> | | | | | | |
|--|-----------------------|--------------------|--------------------|---------------------|----------------|--------------------|-------------|---------|-------------|
| 1/1/2008 | | | | | | | | | |
| 1/31/2008 | 8,847,523 | 44,640 | 198.20 | | | | | | |
| 2/29/2008 | 7,781,474 | 41,760 | 186.34 | | | | | | |
| 3/31/2008 | 6,022,200 | 44,640 | 134.91 | | | | | | |
| 4/30/2008 | 8,117,600 | 43,200 | 187.91 | | | | | | |
| 5/31/2008 | 8,086,200 | 44,640 | 181.14 | | | | | | |
| 6/30/2008 | 11,233,200 | 43,200 | 260.03 | | | | | | |
| 7/31/2008 | 9,011,600 | 44,640 | 201.87 | | | | | | |
| 8/31/2008 | 9,214,000 | 44,640 | 206.41 | | | | | | |
| 9/30/2008 | 9,422,000 | 43,200 | 218.10 | | | | | | |
| 10/31/2008 | 9,063,300 | 44,640 | 203.03 | | | | | | |
| 11/30/2008 | 8,522,324 | 43,200 | 197.28 | | | | | | |
| 12/31/2008 | 10,223,422 | 44,640 | 229.02 | | | | | | |
| | | | | | | | | | |
| <table border="1"><tr><td><u>TOTAL GAL.S.</u></td><td><u>MINUTES</u></td><td><u>AVG. G.P.M.</u></td></tr><tr><td>105,544,843</td><td>527,040</td><td>200.2596444</td></tr></table> | | | | <u>TOTAL GAL.S.</u> | <u>MINUTES</u> | <u>AVG. G.P.M.</u> | 105,544,843 | 527,040 | 200.2596444 |
| <u>TOTAL GAL.S.</u> | <u>MINUTES</u> | <u>AVG. G.P.M.</u> | | | | | | | |
| 105,544,843 | 527,040 | 200.2596444 | | | | | | | |

Big Game Road Kill Fatality Report

| Year | 1st Quarter | | 2nd Quarter | | 3rd Quarter | | 4th Quarter | | Total | |
|------|-----------------|--------------|-----------------|--------------|-----------------|--------------|-----------------|--------------|-------|---|
| | Employee Killed | Other Killed | Employee Killed | Other Killed | Employee Killed | Other Killed | Employee Killed | Other Killed | | |
| 1998 | | | | | | | | | | |
| Deer | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | * |
| Elk | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | * |
| 1999 | | | | | | | | | | |
| Deer | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | * |
| Elk | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | * |
| 2000 | | | | | | | | | | |
| Deer | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 2 | 2 | * |
| Elk | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | * |
| 2001 | | | | | | | | | | |
| Deer | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | |
| Elk | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | |
| 2002 | | | | | | | | | | |
| Deer | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | |
| Elk | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | |
| 2003 | | | | | | | | | | |
| Deer | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | |
| Elk | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | |
| 2004 | | | | | | | | | | |
| Deer | 0 | 1 | 1 | 0 | 0 | 0 | 0 | 1 | 3 | |
| Elk | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | |
| 2005 | | | | | | | | | | |
| Deer | 0 | 2 | 1 | 0 | 0 | 0 | 0 | 2 | 5 | |
| Elk | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | |
| 2006 | | | | | | | | | | |
| Deer | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | |
| Elk | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | |
| 2007 | | | | | | | | | | |
| Deer | 0 | 0 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | |
| Elk | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | |
| 2008 | | | | | | | | | | |
| Deer | 0 | 1 | 1 | 0 | 0 | 0 | 0 | 1 | 3 | |
| Elk | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | |
| 2009 | | | | | | | | | | |
| Deer | 0 | 2 | 1 | 1 | 0 | 0 | 0 | 1 | 5 | |
| Elk | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | |

* - Totals verified by Derris Jones - DWR (Habitat Manager) 11/08/00

APPENDIX C

Legal Financial, Compliance and Related Information

Annual Report of Officers
As submitted to the Utah Department of Commerce

Other change in ownership and control information
As required under R645-301-110

CONTENTS

APPENDIX D

Mine Maps

As required under R645-302-525-270

CONTENTS

HORIZON MINE 2009 MINING & 5 YEAR MINE PLAN WITH SUBSIDENCE POINTS

APPENDIX E

Other Information

In accordance with the requirements of R645-301 and R645-302

CONTENTS
HORIZON WELL MONITORING DATA

TABLE 7-1 (Continued)

WATER-LEVEL DATA OBTAINED FROM
LOCAL MONITORING WELLS

| Date | HZ-95-1 | | HZ-95-1S | | HZ-95-2 | | HZ-95-3 | | HZ-01-06-1 | |
|-------------|----------------|-------------------|----------------|-------------------|----------------|-------------------|----------------|-------------------|----------------|-------------------|
| | Depth (ft)* | Elevation (ft) | Depth (ft)* | Elevation (ft) | Depth (ft)* | Elevation (ft) | Depth (ft)* | Elevation (ft) | Depth (ft)* | Elevation (ft) |
| 12/5/95 | -- | -- | 135.0 | 8221.5 | 828.0 | 7519.6 | -- | -- | | |
| 12/13/95 | 786.00 | 7570.70 | -- | -- | -- | -- | -- | -- | | |
| 12/21/95 | -- | -- | -- | -- | -- | -- | 378.80 | 7522.70 | | |
| 7/9-10/96 | 711.30 | 7585.40 | 133.80 | 8222.70 | 830.00 | 7517.60 | 380.80 | 7520.70 | | |
| 8/5/96 | 770.80 | 7585.90 | 133.50 | 8223.00 | 829.40 | 7518.20 | 387.80 | 7513.70 | | |
| 9/11/96 | 769.40 | 7587.30 | 132.50 | 8224.00 | 829.40 | 7518.20 | 387.70 | 7513.80 | | |
| 10/23/96 | 776.40 | 7580.30 | 132.50 | 8224.00 | 829.20 | 7518.40 | 380.70 | 7520.80 | | |
| 11/1/96 | 776.40 | 7580.30 | 132.50 | 8224.00 | 829.20 | 7518.40 | 380.80 | 7520.70 | | |
| 12/13/96 | # | | # | | 829.50 | 7518.10 | 379.50 | 7522.00 | | |
| 1/6/97 | 771.05 | 7584.75 | 133.00 | 8223.50 | | | | | | |
| 2/10/97 | + | | + | | + | | + | | | |
| 3/25/97 | + | | + | | + | | + | | | |
| 4/1/97 | + | | + | | + | | + | | | |
| 5/28/97 | 770.95 | 7584.90 | 131.50 | 8225.10 | 828.05 | 7519.55 | 379.90 | 7522.40 | | |
| 6/30/97 | 770.20 | 7585.60 | 132.14 | 8224.36 | 827.72 | 7519.88 | 379.90 | 7522.40 | | |
| 9/16/97 | 773.50 | 7583.90 | 132.50 | 8224.00 | 827.20 | 7520.40 | 379.90 | 7522.40 | | |
| 10/17/97 | 773.70 | 7583.70 | 132.50 | 8224.00 | 827.20 | 7520.40 | 379.90 | 7522.40 | | |
| 6/30/98 | 817.80 | 7538.90 | 133.10 | 8223.40 | 836.60 | 7511.00 | 395.10 | 7506.40 | | |
| 9/1/98 | 745.00 | 7611.70 | 134.50 | 8222.00 | 840.90 | 7506.70 | 398.00 | 7503.50 | | |
| 6/1/99 | 758.80 | 7597.90 | 133.70 | 8222.80 | 847.80 | 7499.80 | 399.50 | 7502.00 | | |
| 7/1/99 | 758.10 | 7598.60 | 134.40 | 8222.10 | 845.90 | 7501.70 | | | | |
| 11/1/99 | + | | + | | + | | 397.00 | 7504.50 | | |
| 5/20/00 | 862.70 | 7494.00 | 132.80 | 8223.70 | 849.80 | 7497.80 | 401.50 | 7500.00 | | |
| 9/8/00 | | | | | | | 402.10 | 7499.40 | | |
| 9/26/00 | 875.00 | 7481.70 | 134.40 | 8222.10 | 863.80 | 7483.80 | | | | |
| 10-12/31/00 | \$ | | \$ | | \$ | | \$ | | | |
| 12/12/00 | + | | + | | + | | + | | | |
| 3/23/01 | + | | + | | + | | + | | | |
| 5/31-6/1/01 | 870.55 | 7486.15 | 133.75 | 8222.75 | 856.75 | 7490.85 | 414.17 | 7487.33 | | |
| 9/20/01 | 876.85 | 7479.85 | 134.50 | 8222.00 | 862.40 | 7485.20 | 416.10 | 7485.40 | | |
| 10/19/01 | 873.36 | 7483.34 | 134.65 | 8221.85 | 858.71 | 7488.89 | 415.70 | 7485.80 | | |
| 11/17/01 | | | | | | | | | 944.20 | 7817.20 |
| 2/18/02 | @ | | @ | | @ | | @ | | @ | |
| 3/25/02 | @ | | @ | | @ | | @ | | @ | |
| 6/12/02 | 876.68 | 7480.02 | 135.08 | 8221.42 | 867.38 | 7480.22 | 458.12 | 7443.38 | 1029.58 | 7731.82 |
| 9/4/02 | 876.85 | 7479.85 | 136.37 | 8220.13 | 869.28 | 7478.32 | %465.1 | %7436.4 | 1036.85 | 7724.55 |
| 10/8/02 | 876.55 | 7480.15 | 136.00 | 8220.50 | 869.65 | 7477.95 | %465.1 | %7436.4 | 1037.45 | 7723.95 |
| 5/14/2003 | @ | | @ | | @ | | %465.1 | %7436.4 | @ | |
| 5/28/2003 | 875.12 | 7481.38 | 135.35 | 8221.15 | 872.00 | 7475.60 | %465.1 | %7436.4 | 1036.6 | 7724.80 |
| 9/5/2003 | 876.22 | 7480.48 | 135.51 | 8220.99 | 871.73 | 7475.87 | %465.1 | %7436.4 | 1036.74 | 7724.66 |
| 10/16/2003 | 876.24 | 7480.46 | 135.45 | 8220.93 | 871.92 | 7476.06 | %465.1 | %7436.4 | 1036.5 | 7724.46 |
| 3/1/2004 | @ | | @ | | @ | | | | @ | |
| 3/29/2004 | @ | | @ | | @ | | %465.1 | %7436.4 | | |
| 6/18/2004 | 901.54 | 7455.16 | 135.68 | 8220.82 | 877.20 | 7470.40 | %465.1 | %7436.4 | 1062.50 | 7698.90 |
| 9/27/2004 | 905.72 | 7450.98 | 136.15 | 8220.35 | 878.00 | 7469.60 | %465.1 | %7436.4 | 1050.55 | 7710.85 |
| 10/14/2004 | 909.25 | 7447.45 | 135.90 | 8220.60 | 878.17 | 7469.43 | %465.1 | %7436.4 | 1050.33 | 7711.07 |
| 3/16/2005 | @ | | @ | | @ | | @ | | @ | |
| 3/31/2005 | @ | | @ | | @ | | @ | | @ | |
| 6/28/2005 | 993.51 | 7363.19 | 132.90 | 8223.70 | 882.62 | 7464.98 | %465.1 | %7436.4 | 1039.76 | 7721.64 |
| 9/22/2005 | 993.67 | 7363.03 | 133.90 | 8222.60 | 844.50 | 7503.10 | %465.1 | %7436.4 | 1039.91 | 7721.49 |
| 10/13/2005 | 993.61 | 7363.09 | 135.82 | 8211.78 | 844.61 | 7502.99 | %465.1 | %7436.4 | 1039.80 | 7721.60 |
| 3/31/2006 | @ | | @ | | @ | | @ | | @ | |
| 6/23/2006 | 999.13 | 7357.60 | 143.61 | 8212.90 | 887.24 | 7460.40 | %465.1 | %7436.4 | 1039.20 | 7722.20 |

% Dry

| | Casing | Tubing | Elevation |
|------------|--------|--------|-----------|
| HZ-95-1 | 8357.1 | 8356.7 | 8352.6 |
| HZ-95-1S | 8357.6 | 8356.5 | 8352.6 |
| HZ-95-2 | 8348.1 | 8347.6 | 8346.3 |
| HZ-95-3 | 7902.2 | 7901.5 | 7897.6 |
| HZ-01-06-1 | | 8761.4 | 8759.4 |

WATER-LEVEL DATA OBTAINED FROM LOCAL MONITORING WELLS

[illegible]